



Post-test Inspection of NASA's Evolutionary Xenon Thruster Long-Duration Test Hardware: Discharge Chamber


Rohit Shastry and George C. Soulas

NASA Glenn Research Center, Cleveland, OH 44135, USA

Presented at the 52nd AIAA/SAE/ASEE Joint Propulsion Conference

July 25, 2016

Additional NEXT Publications





- LDT Companion Papers
 - Post-test Examination of NASA's Evolutionary Xenon Thruster Long-Duration Test Hardware: Discharge and Neutralizer Cathodes, AIAA-2016-4631
 - EP-09 4:00 – 4:30 PM on 7/25 in 250 D
 - Post-test Examination of NASA's Evolutionary Xenon Thruster Long-Duration Test Hardware: Ion Optics, AIAA-2016-4632
 - EP-09 4:30 – 5:00 PM on 7/25 in 250 D
- Development and Validation of Autonomous Operational Sequences for the NEXT System, AIAA-2016-5077
 - ITAR-04 5:00 – 5:30 PM on 7/27 in 151 DE
- Status of the Development of Flight Power Processing Units for the NASA's Evolutionary Xenon Thruster - Commercial (NEXT-C) Project, AIAA-2016-4519
 - APS-01 10:30 – 11:00 AM on 7/25 in 150 DE

Presentation Outline




- NEXT Long-Duration Test (LDT) Background
- Discharge Chamber Magnetic Field Measurements
- Inspection of Discharge Chamber Mesh
- Discharge Chamber Flakes
- High-Voltage Propellant Isolators
- Insulators and Electrical Cabling
 - Screen-Anode Low Impedance Resolution
- Summary and Future Work

NEXT LDT Background



- Initiated as part of a comprehensive thruster service life assessment, utilizing both testing and modeling analyses, comprised of:
 - NEXT 2,000 h EM thruster wear test
 - NEXT thruster service life model development
 - NEXT PM1R thruster and propellant management system wear test
 - NEXT LDT
- Goals of the NEXT LDT
 - Qualify the NEXT thruster propellant throughput capability to an initial value of 450 kg
 - Validate the thruster service life models
 - Characterize thruster performance over test duration
 - Measure critical thruster component erosion rates
 - Identify unknown life-limiting mechanisms
- Objective to demonstrate 450 kg throughput redefined after completion in December 2009 to test-to-failure of thruster or voluntary test termination

NEXT LDT Background



- Decision to voluntarily terminate test was made in April 2013
- A comprehensive end-of-test performance characterization along with diagnostic repairs were performed prior to test termination in February 2014
- At end of test, thruster had demonstrated:
 - 51,184 hours of operation
 - 918 kg propellant throughput
 - 35.5 MN-s total impulse
- Thruster vented to atmosphere in April 2014, with post-test inspection beginning shortly thereafter
- Post-test inspection is presently nearing completion – this paper/presentation discusses pertinent results to-date of the discharge chamber as well as miscellaneous components such as the high-voltage propellant isolators (HVPIs) and electrical cabling
 - Results on other components are covered in companion papers



NEXT LDT Post-test Inspection




- Post-test inspection of NEXT LDT thruster hardware largely followed similar methods and procedures as what was used for NSTAR ELT
- Comparisons made (when appropriate) to results from several prior life tests
- Focus placed on previously identified failure modes, including:
 - Magnetic field degradation due to excessive temperatures
 - Poor flake retention of sputtered material
 - Deposition of sputtered material on insulators, including within HVPIs
- Also needed to resolve issues encountered during test, including an observed low impedance between the anode (discharge chamber) and screen grid

Magnetic Field Measurements




- Magnetic field measurements were taken with a 3-axis gaussmeter within the volume of the discharge chamber
 - Identical technique and equipment as pretest measurement
- Comparison of strength profile at chamber centerline indicates pretest and post-test measurements are all within 6 G of each other
- Largest discrepancies occur furthest upstream where there are large B_{mag} and $\partial B/\partial z$
 - Position uncertainty, especially of $z = 0$, could lead to larger differences in this region
- Analysis of the volumetric map as a whole shows no sign of magnetic field degradation



Magnetic Field Measurements





- Measurements of magnetic field strength were also made at various azimuthal locations along each magnet ring, similar to pretest measurements
 - Measurement was found to be sensitive to relative probe angle and location along discrete magnets
 - These factors were varied until the strength was maximized, yielding a repeatable measurement – however, pretest measurements were not taken this way
- When comparing maximum values along each ring, pretest and post-test measurements agree to within $\pm 6\%$, with post-test being higher most of the time
- All measurements consistent with thruster discharge performance data, indicating no magnetic field degradation




Discharge Chamber Mesh



- Discharge chamber mesh samples were removed at various axial locations and a fixed azimuthal location (axisymmetry of deposition assumed)
- Deposition coating evident in photomicrographs of mesh
- Energy dispersive x-ray spectroscopy indicates this coating is primarily grid material, although numerous nodules within mesh had high carbon content
- Similar results were found in NSTAR ELT



From NEXT LDT




From NSTAR ELT*

*Image from Sengupta, A., et al., "The 30,000-Hour Extended-Life Test of the Deep Space 1 Flight Spare Ion Thruster," NASA/TP 2004-213391, March, 2005.

Discharge Chamber Mesh



- Samples of discharge chamber mesh further upstream showed deposition with broken edges
 - Could be due to spalling or handling of sample during inspection
- Broken edge shows layered deposition
 - Backscattered electron image indicates light layers are primarily grid material and darker layers have more carbon content
- Estimate of deposition thickness from broken edge $\sim 15\text{ }\mu\text{m}$, which is well below estimated maximum deposition thickness that can be retained by mesh



Discharge Chamber Flakes



- A large number of flakes were found at the bottom of the discharge chamber
 - Similar result to NSTAR ELT
- Numerous samples were taken, and a total of ~ 3.1 grams of material was collected from the discharge chamber
- Many of the largest flakes exhibited a semi-circular shape
 - Radius of curvature of these flakes indicate they had come from the accelerator grid apertures – similar result to NSTAR ELT
- Flakes were comprised of a combination of grid material and carbon




From NEXT LDT





From NSTAR ELT*

*Image from Sengupta, A., et al., "The 30,000-Hour Extended-Life Test of the Deep Space 1 Flight Spare Ion Thruster," NASA/TP 2004-213391, March, 2005.

Discharge Chamber Flakes




- Samples of flakes from different axial locations were analyzed to determine size distributions
 - Need to quantify likelihood of forming flakes large enough to short grids
- Histograms indicate that 99% of flakes have a largest dimension $< 200 \mu\text{m}$
- However, flakes do exist that are large enough to cause a grid-to-grid short
- NSTAR ELT also found large flakes, but determined that these flakes originated from the facility so should not be an issue in flight
 - Similar analysis on large flakes for NEXT LDT is presently underway



High-Voltage Propellant Isolators



- HVPIs for both main and discharge cathode lines were inspected for leaks and impedance degradation
- No leaks were found, and both HVPIs had impedances $> 300 \text{ G}\Omega$ at 1800 V applied voltage




- Only visual change on casing was discoloration on downstream end of discharge cathode HVPI
 - Cause is unknown, but was not an issue
- Destructive disassembly of both HVPIs revealed all insulators to be clean with no signs of internal arcing

Insulators and Electrical Cabling




- Numerous insulators on thruster were inspected for signs of arcing or impedance degradation including:
 - Discharge cathode wiring insulators
 - Ion optics mounting isolators
 - Thruster gimbal insulators
 - Neutralizer cathode assembly mounting insulators
- All insulators were found to be in excellent condition with no signs of arcing
 - All impedances $> 300 \text{ G}\Omega$ at maximum operating voltages
- All electrical cabling was also inspected for signs of arcing or breaks in insulation
- A few breaks in outer insulation jacket were found in the anode and accelerator grid cables, but inner insulation remained intact
 - Proper isolation from surroundings at maximum operating voltages was verified
- All other cabling was found to be intact with no signs of arcing


Screen-Anode Low Impedance



- Low impedance between screen grid and anode was observed during test, and dropped to 40-50 k Ω by the end of the test
- Cause was traced to deposition on screen grid wire as it passes through discharge chamber from rear of thruster (verified with resistance measurements)
- Elemental analysis indicated this deposition is primarily backspattered carbon from the facility that had come through the perforated plasma screen
- Cylindrical plasma screen is solid in latest thruster design, so this issue is not expected to occur in flight or in future ground tests



Summary and Future Work



- Post-test inspection of the LDT thruster hardware is nearing completion
- Major findings
 - No sign of magnetic field degradation after 51 kh of operation
 - Deposition on discharge chamber mesh is $\sim 15 \mu\text{m}$, much less than the estimated maximum retainable thickness
 - Large amount of flakes found at bottom of discharge chamber, including certain large ones that had spalled from accelerator grid apertures
 - Size distributions of flakes indicate that 99% have largest dimensions less than $200 \mu\text{m}$, much smaller than the grid gap
 - All insulators and electrical wiring inspected with no signs of arcing found
 - Screen grid-anode low impedance traced to deposition on screen grid wire from facility backspattered material and should not occur in flight
- Future Work
 - Discharge chamber mesh samples will be sectioned to further analyze deposition
 - Chamber flakes will be more thoroughly characterized to quantify amount and size of flakes that originated outside of thruster

Questions?

